

Fig.1




Fig.2

DETERIORATION OF WAVEFORM AFTER
PASSING THROUGH GATE(2.4Gbps NRZ2¹⁵⁻¹)




Fig.3




Fig.4




Fig.5




Fig.6




Fig.8




Fig.9




Fig. 11




Fig.12




Fig.13




Fig.14




Fig. 15




Fig.16




Fig.17




Fig.18

